



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: April 21, 1988
2:00 PM - 4:30 PM

Permittee and/or Operators Name: Genwal Coal Company
Business Address: P.O. Box 1201, Huntington, Utah 84527
Mine Name: Crandall Canyon Permit Number: ACT/015/032
Type of Mining Activity: Underground XX Surface Other
County: Emery
Company Official(s): Lannie Burnside, Surface Operator
State Official(s): James Leatherwood, Sue Linner, and Harold Sandbeck
Partial: XX Complete: Date of Last Inspection: March 24, 1988
Weather Conditions: cold, overcast and hail
Acreage: Permitted 164.4 Disturbed 5.75 Regraded 0.5 Seeded 0.5 Bonded 5.75
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/032

DATE OF INSPECTION April 21, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers. The operator has installed the new speed limit signs along side the Forest Service access road as required by the Forest Service Special Use Permit.

3. Topsoil. All three topsoil stockpiles were inspected. Each topsoil stockpile is stable. Vegetative growth is good. There was no noticeable emergence of any seedlings from the previous falls reseeding efforts on the south facing aspects of the two topsoil stockpiles located closest to the mine site. These two stockpiles will be evaluated further during the Divisions vegetative cover density survey scheduled in June.


4. Hydrologic Balance:

b. Diversions. A minimal amount of earthen materials has eroded from the adjacent upslope into the lower part of UD-2. The diversion was functional at the time of inspection. The operator was notified about the required maintenance. Mr. Burnside stated it would be taken care of before the end of the month.

Copy of this Report:

Mailed to: A. King - Genwal Coal; John Kathmann - OSM

Given to: J. Helfrich - DOGM

Inspectors Signature and Number:  #16 Date: 05/3/88